



LINDY®

CONNECTION PERFECTION



Attaching the Connector





Place the LC Connector into one half of the LC Lock



Rotate the LC Connector until it clicks into place




Repeat these steps for the 2nd Connector




Insert the completed Connector into the LC Port

Removal from the LC port



Insert the removal Key until it clicks



Holding Connector & Key together pull them out

